

Pricelist 2019

prices valid from 21. Mrz 19

Issue: EN-PreisS-0003-B

/ 18.03.2019

Repair & Overhaul

				Preis incl. VAT. (19%)
3/4-hand watches <i>Revision</i>	Serie 90/90E	Calibre UNITAS	StandardrevisionPlus	171 €
	Serie 31*/31E	Calibre HS81	StandardrevisionPlus	200 €
	Serie 31 with rot. bezel	Calibre HS81	Standardrevision	179 €
	Serie 31/Datum	Calibre HS81 with date indication	Standardrevision	182 €
	WZU	Calibre HS81	WZU Standardrevision	224 €
			Teilreparatur Grundpreis	48 €
			StandardrevisionPlus	250 €
	Pocket watch	HS81	Standardrevision	200 €
	self winding movement, 3 hands	Calibre ETA 2824, 2892, SW220	Standardrevision	185 €
	self winding movement, 3 hands	Calibre ETA 2892 with modul	Standardrevision	200 €
	self winding movement, 4 hands	GU-220	StandardrevisionPlus2018	215 €

Chronographs <i>Revision</i>	Flying Officer	Valjoux 7760	StandardrevisionPlus	301 €
			Standardrevision	265 €
	60.50, 40.50, 41.50	Valjoux 7750	StandardrevisionPlus2018	325 €
	Büren12	Büren12	Standardrevision	325 €
	Serie 20/21	Valjoux 7750	Standardrevision	295 €

*covers the update to a new style crown

Standard overhaul services "Standardrevision"

Factory overhaul (disassembling, cleaning, lubricating, re-assembling and adjusting of the movement, replacement of main spring - only for chronograph movements. Renewing of the seal system (seal-ring of the crown, pushers, case back)
 Cleaning of the case
 Cleaning and checking of the solid strap (no replacement of the clasp, if necessary and possible, replacement of split pins and spring bars)
 Final inspection (Functionality Tests, test on time grapher, water resistance test)

StandardPlus overhaul services "StandardrevisionPlus" (addition to Standardrevision)

Replacing the winding crown

StandardPlus overhaul services "Standardrevision2018" (addition to Standardrevision)

replacement of the ball bearing and reversing wheel

StandardPlus overhaul services "StandardrevisionPlus2018" (addition to Standardrevision)

Replacing the winding crown and tube
 replacement of the ball bearing and reversing wheel
 replacement of the glass seal(s)

Note: The parts removed during an inspection / repair are scrapped by Guinand

Repairs at cost	repairs beside a standard overhaul	Base price	50 €
	will be claculated at cost		
Reconditioning & Modifications	Reconditioning of the case when ordered together withstandard overhaul		100 €
	Reconditioning of the case when ordered seperately		130 €
	polishing the front or back glas (n.a. for sapphire glass)		11 €
	Hands in contrasting color (not luminescent)		45 €
	Glucydur balance and Nivarox hairspring for VJ7750 in exchange to standard balance		98 €
	Days of week in English (VJ7750)		26 €

Shipping costs

within Germany (Insured shipping of watches, return shipping label) Customer --> Guinand	12,5 €
within Germany (Insured shipping of watches) Guinand --> Customer	12,5 €
Spare parts (within Germany)	5,0 €
Outside Germany we deliver (Insured shipping) to the following countries: EU (Kroatia, Malta excluded), Switzerland, Norway	50,0 €
Note: Greece (only mainland), Portugal (Azores and Madeira excluded) Spain (Canary Islands, Ceuta and Melilla excluded) Great Britain (England , Northern Ireland, Scotland , Wales) Other countries (Shipping possibility please inquire in individual cases)	65 €

Cost estimate

Cost estimate before starting any service (counted towards the invoice amount in favour of the Customer if the order is fulfilled) 20 €

pilot bezel for SFL 145 €

spare parts for metal straps

clasp for Typ H satinized	49 €
clasp for Typ H mat	49 €
bracelet end link Typ H satinized/polished	15 €
bracelet end link Typ H mat	15 €
bracelet link Thyp H sat./pol. (incl. screw)	10 €
bracelet link Thyp H matte (incl. screw)	10 €
screw for bracelet link polished	2,5 €
screw for bracelet link mat	2,5 €